


Military Packaging Pilot Status

Cycle Time Reduction



Warranty Returns


	baseline.	2000	2001YTD
Number of Pieces Shipped	415K	234K	219K
Number of Warranty Returns	2	0	0
Percentage of Warranty Returns	0%	0%	0%

Currently monitoring warranty to detect any packaging related discrepancies

Packaging Innovations Underway

Innovation Description	Status
- 5S Phoenix Shipping area	80 % on redesigned
- Fast Pack to PCI insert	Report due mid-J uly
- Special Packaging Instructions Review	Phoenix due 4Q01
- Standardize supplier pack material	Working on SPOC 239


Packaging Costs



Honeywell

Military Packaging Pilot Status

Cycle Time Reduction



Warranty Returns


	baseline.	2000	2001YTD
Number of Pieces Shipped	415K	234K	219K
Number of Warranty Returns	2	0	0
Percentage of Warranty Returns	0%	0%	0%

Currently monitoring warranty to detect any packaging related discrepancies

Packaging Innovations Underway

Innovation Description	Status
- 5S Phoenix Shipping area	80 % on redesigned
- Fast Pack to PCI insert	Report due mid-J uly
- Special Packaging Instructions Review	Phoenix due 4Q01
- Standardize supplier pack material	Working on SPOC 239


Packaging Costs



Honeywell

Military Packaging Pilot Status

Cycle Time Reduction



Warranty Returns


	baseline.	2000	2001YTD
Number of Pieces Shipped	415K	234K	219K
Number of Warranty Returns	2	0	0
Percentage of Warranty Returns	0%	0%	0%

Currently monitoring warranty to detect any packaging related discrepancies

Packaging Innovations Underway

Innovation Description	Status
- 5S Phoenix Shipping area	80 % on redesigned
- Fast Pack to PCI insert	Report due mid-J uly
- Special Packaging Instructions Review	Phoenix due 4Q01
- Standardize supplier pack material	Working on SPOC 239

Packaging Costs



Honeywell